


GLIPIC BOARD Ver D and GLADPS2 adapter PINOUTS
COMPSys - Jan 2002



- +
7 to 16v DC supply

- 1 - Make sure all components are oriented correctly and have the correct values.
- 2 - Double check all soldered joints
- 3 - Check continuity (with power off) between the PIC pins and the LCD connection pins on the adapter.
- 4 - Apply power and check the negative voltage on the Pin 4 (LCD side) of the adapter. Rotate the POT to check voltage swing.